



ABERDEEN LIFTING SERVICES LTD

CERTIFICATE OF TEST, EXAMINATION AND INSPECTION REPORT

SI 2306 SI 2307

CLIENT:	BLUE MANTA 6 KIRKTON AVENUE PITMEDDEN RD IND EST DYCE ABERDEEN AB21 0BF	TEST HOUSE:	ABERDEEN LIFTING SERVICES LTD UNITS 7&8 WOODLANDS ROAD KIRKHILL INDUSTRIAL ESTATE, DYCE ABERDEEN AB21 0GX TEL: 01224 723333 FAX: 01224 723311
P.O. NO:		REQUISITION NO:	
CERT NO:	A7037-01	INSPECTION DATE:	23/05/2008


SERIAL NO:	QTY	DESCRIPTION	SWL/PAYLOAD	PROOF LOAD
BM-SP-3610	1	MEDIUM SPOOLER UNIT TO DNV2.7-1 1200MM x 1500MM x 1440MM ALL WELDED STEEL CONSTRUCTION 4 TOP CORNER PADEYES TARE WT: 700 KGS GROSS WT: 2000 KGS 4 POINT TEST	1300 KGS	5000 KGS

M.P.I INSPECTION DETAILS

PROCEDURE:	ALS MPI 01	EQUIPMENT:	Y6 YOKE	METHOD:	WET CONTINUOUS
SPECIFICATION:	BS EN 1290	MEDIA:	NPT 16 WHITE PAINT	INSPECTOR:	B SMART
MATERIAL:	WELDED CARBON STEEL	INDICATOR:	BLACK INK	QUALS:	SNT 11

RESULTS: A MAGNETIC PARTICLE INSPECTION WAS CARRIED OUT ON LIFTING POINT WELDMENTS. ON THE EQUIPMENT NO CRACK OR CRACKLIKE INDICATIONS WERE NOTED AT TIME OF INSPECTION.

DECLARATION: I HEREBY DECLARE THAT THE ABOVE INFORMATION IS CORRECT AND THE EQUIPMENT HAS BEEN TESTED AND THOROUGHLY EXAMINED IN ACCORDANCE WITH THE APPROPRIATE PROVISIONS AND IS FREE FROM DEFECTS AFFECTING SAFETY.

	COMPLETED BY
ENGINEER	B SMART
SIGNATURE	
DATE	23/05/2008

NEXT INSPECTION DATE: 22/11/2008
DATE OF MANUFACTURE: MAY 2008

Initials 
Lloyd's Register EMEA
Aberdeen Office

Lloyd's
Register



ABERDEEN LIFTING SERVICES LTD

MAGNETIC PARTICLE INSPECTION REPORT

CUSTOMER: BLUE MANTA	LOCATION: ALS YARD
P.O. No:	CERT No: A7037-06
JOB No:	DATE OF INSP: 23/05/2008

JOB DESCRIPTION:

100% MAGNETIC PARTICLE INSPECTION WAS CARRIED OUT PRE& POST LOAD TEST ON ALL LOAD BEARING WELDS AND 20% SECONDARY WELDS

ITEM: MEDIUM SPOOLER UNIT	
QUANTITY: 1	SURFACE: AS WELDED
SERIAL No: BM-SP-3610	EQUIPMENT: Y6 YOKE
DRG. No:	MEDIA: NPT 16 WHITE PAINT
MATERIAL: CARBON STEEL	INDICATOR: BLACK INK
PROCEDURE: ALS M.P.I. 01	METHOD: WET CONTINUOUS
SPECIFICATION: BS EN 1290	

RESULTS: NO CRACK OR CRACKLIKE INDICATIONS ARE NOTED AT TIME OF INSPECTION.

	COMPLETED BY
ENGINEER/TECHNICIAN	B.SMART
SIGNATURE	<i>PP. YH Perltay</i>
DATE	23/05/2008