



Hendrik Veder Group Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	REPORT OF THOROUGH EXAMINATION (AND CERTIFICATE OF TEST IF APPLICABLE) The Lifting Operations and Lifting Equipment Regulations SI2307:1998 The Merchant Shipping and Vessels (Lifting Operations and Lifting Equipment) Regulations SI2148:2006 The Merchant Shipping and Fishing Vessels (Lifting Operations and Lifting Equipment)(Amendment) Regulations SI2166:2008						Report Number	50091/15
							Date Of Report	02/11/2022
							Date Of Examination	02/11/2022
							Customer PO Number	41035
Quantity & Description of Equipment	Manufacturer & Date Of Manufacture (if Known)	Working Load Limit	Proof Load Applied	First Examination YES / NO	Date of Last Thorough Examination	Date of Next Thorough Examination	Next Test Date	Test Certificate Number
PIPE BASKET TO DNV2.7-1/BS EN 12079 13.92 M x 1.44 M x 1.6 M WELDED STEEL CONSTRUCTION 4 TOP CORNER LIFTING POINTS TARE WEIGHT: 5000 KGS GROSS WEIGHT: 16500 KGS	REMPRODEX 11/2007 75487	11500 KGS	N/A	NO	07/07/2022	02/05/2023	N/A	48628/34
FOUR LEG WIRE ROPE SLING ASSEMBLY TO DNV 2.7-1 4 LEGS 4.66 M x 28 MM DIA IWRC GALV CONNECTED VIA HA36QA QUAD ASSEMBLY	UNKNOWN	16.5 TONNE 0-45°	N/A	NO	07/07/2022	02/05/2023	N/A	48628/34
G4163-SAFETY PIN BOW SHACKLES	VAN BEEST	12 TONNE	N/A	NO	07/07/2022	02/05/2023	N/A	48628/34
SERIAL NUMBER(S)	UNIT BM-B-4519 SLING BM-B-4519/1 SHACKLES 19/2-5							
Particulars Of Defects which are a Danger to persons or 'None'	Particulars of any Defects or 'None'		Date by which other Defects are to be repaired		Particulars of any Repair, alterations to remedy Defect or 'None'		Particulars of any Observations	
NONE	NONE		N/A		NONE		N/A	
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:		Name, Address and qualifications of person who carried out the examination:		Name, Address of person signing the report on behalf of its author:		Reference Number	
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 0BF	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 0BF		S.GACH COMPANY APPOINTED EXAMINER		STEWART GROVES UK OPERATIONS MANAGER		50091	
							Customer Order Number	
							41035	
Signature of the person who carried out the examination			Signature on behalf of author for Hendrik Veder Group UK Ltd					
I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'								

Hendrik Veder Group Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	NON DESTRUCT EXAMINATION REPORT		Report Number	50091/15A
			Date Of Report	02/11/2022
			Date Of Examination	02/11/2022
			Customer PO Number	41035
Job Description	Equipment Description		Serial Number(s)	
100% MPI CARRIED OUT ON ALL LIFT POINT WELDS	PIPE BASKET TO DNV2.7-1/BS EN 12079 13.92 M x 1.44 M x 1.6 M WELDED STEEL CONSTRUCTION 4 TOP CORNER LIFTING POINTS TARE WEIGHT: 5000 KGS GROSS WEIGHT: 16500 KGS		BM-B-4519	
Acceptance Standard			Heat Treatment Condition	
BS EN ISO 9934-1 : 2015			MORE THAN 24HOURS POST WELD	
Examination Procedure Number			MATERIAL	
WI4.1			STEEL CONSTRUCTION	
INSPECTION EQUIPMENT USED				
MAGNETIC PARTICLE				
Equipment Type		Contrast Paint		
Y6 YOKE ELECTROMAGNET		WHITE CONTRAST PAINT		
Pole Spacing		Indicator		
ADJUSTABLE		BLACK MAGNETIC INK		
Results		Test Restrictions / Comments		
NO EVIDENCE OF SURFACE DEFECTS FOUND AT TIME OF EXAMINATION		NONE		
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:	Name, Address and qualifications of person who carried out the examination:	Name, Address of person signing the report on behalf of its author:	Reference Number
				50091
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 OB	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 OB	S.GACH ASNT LEVEL 11 COMPANY APPOINTED EXAMINER	STEWART GROVES UK OPERATIONS MANAGER	Customer Order Number
				41035
Signature of the person who carried out the examination		Signature on behalf of author for Hendrik Veder Group UK Ltd		
I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'				

Hendrik Veder Group Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	NON DESTRUCT EXAMINATION REPORT		Report Number	50091/15B
			Date Of Report	02/11/2022
			Date Of Examination	02/11/2022
			Customer PO Number	41035
Job Description	Equipment Description		Serial Number(s)	
100% MPI CARRIED OUT ON ALL MASTER LINK / MASTER LINK ASSEMBLY WELDS	FOUR LEG WIRE ROPE SLING ASSEMBLY TO DNV 2.7-1 4 LEGS 4.66 M x 28 MM DIA IWRC GALV CONNECTED VIA HA36QA QUAD ASSEMBLY ** HA36QA**		BM-B-4519/1	
Acceptance Standard			Heat Treatment Condition	
BSEN ISO 9934-1 : 2015			MORE THAN 24HOURS POST WELD	
Examination Procedure Number			MATERIAL	
WI4.1			STEEL CONSTRUCTION	
INSPECTION EQUIPMENT USED				
MAGNETIC PARTICLE				
Equipment Type		Contrast Paint		
Y6 YOKE ELECTROMAGNET		WHITE CONTRAST PAINT		
Pole Spacing		Indicator		
ADJUSTABLE		BLACK MAGNETIC INK		
Results		Test Restrictions / Comments		
NO EVIDENCE OF SURFACE DEFECTS FOUND AT TIME OF EXAMINATION		NONE		
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:	Name, Address and qualifications of person who carried out the examination:	Name, Address of person signing the report on behalf of its author:	Reference Number
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 OB	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 OB	S.GACH ASNT LEVEL 11 COMPANY APPOINTED EXAMINER	STEWART GROVES UK OPERATIONS MANAGER	50091
				Customer Order Number
				41035
Signature of the person who carried out the examination	<i>S. Gach</i>	Signature on behalf of author for Hendrik Veder Group UK Ltd		<i>S. Groves</i>
I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'				