

 Hendrik Veder Group Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	REPORT OF THOROUGH EXAMINATION (AND CERTIFICATE OF TEST IF APPLICABLE) The Lifting Operations and Lifting Equipment Regulations SI2307:1998 The Merchant Shipping and Vessels (Lifting Operations and Lifting Equipment) Regulations SI2148:2006 The Merchant Shipping and Fishing Vessels (Lifting Operations and Lifting Equipment)(Amendment) Regulations SI2166:2008						Report Number	1726161269/30
							Date Of Report	07/05/2026
							Date Of Examination	07/05/2026
							Customer PO Number	51318
Quantity & Description of Equipment	Manufacturer & Date Of Manufacture (if Known)	Working Load Limit	Proof Load Applied	First Examination YES / NO	Date of Last Thorough Examination	Date of Next Thorough Examination	Next Test Date	Test Certificate Number
55FT CARGO BASKET TO DNV2.7-1:2006 / EN12079:2006 16.83M X 1.22M X 1.1M WELDED STEEL CONSTRUCTION 4 TOP CORNER LIFTING POINTS TARE WEIGHT: 5400 KGS GROSS WEIGHT: 15000 KGS	BLUE MANTA ABN 1004100/4 04/2010	9600 KGS	N/A	NO	11/12/2025	07/11/2026	N/A	1725163382/34
FOUR LEG WIRE ROPE SLING TO DNV2.7-1:2006 LEGS 7.8MTR X 28MM DIA IWRC GALV FITTED TO HA36QA QUAD ASSEMBLY	ABERDEEN LIFTING ALS10075-01 20/06/2024	15 TONNE 0-45°	N/A	NO	11/12/2025	07/11/2026	N/A	1725163382/34
SAFETY PIN BOW SHACKLES	CROSBY	8.5 TONNE	N/A	NO	11/12/2025	07/11/2026	N/A	1725163382/34
SERIAL NUMBER(S)	UNIT: BM-B-5506 SLING: BM-B-5506/1A SHACKLES: 06/2B, 3C, 4D & 5E							
Particulars Of Defects which are a Danger to persons or 'None'	Particulars of any Defects or 'None'		Date by which other Defects are to be repaired		Particulars of any Repair, alterations to remedy Defect or 'None'		Particulars of any Observations	
NONE	NONE		N/A		NONE		N/A	
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:		Name, Address and qualifications of person who carried out the examination:		Name, Address of person signing the report on behalf of its author:		Reference Number	
							1726161269	
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industrial Estate Dyce Aberdeen AB21 0BF	Halliburton Forties Road Montrose DD10 9ET		M. YOUNGSON COMPANY APPOINTED EXAMINER		STEWART GROVES UK OPERATIONS MANAGER		Customer Order Number	
							51318	
Signature of the person who carried out the examination			Signature on behalf of author for Hendrik Veder Group UK Ltd					
I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'								

 Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	NON DESTRUCT EXAMINATION REPORT		Report Number	1726161269/30A
			Date Of Report	07/05/2026
			Date Of Examination	07/05/2026
			Customer PO Number	51318
Job Description	Equipment Description		Serial Number(s)	
100% MPI CARRIED OUT ON ALL LIFT POINT WELDS	55FT CARGO BASKET TO DNV2.7-1:2006 / EN12079:2006 16.83M X 1.22M X 1.1M WELDED STEEL CONSTRUCTION 4 TOP CORNER LIFTING POINTS TARE WEIGHT: 5400 KGS GROSS WEIGHT: 15000 KGS		BM-B-5506	
Acceptance Standard			Heat Treatment Condition	
BSEN ISO 9934-1 : 2016			MORE THAN 24HOURS POST WELD	
Examination Procedure Number			MATERIAL	
WI4.1			STEEL CONSTRUCTION	
INSPECTION EQUIPMENT USED				
MAGNETIC PARTICLE				
Equipment Type		Contrast Paint		
Y6 YOKE ELECTROMAGNET		WHITE CONTRAST PAINT		
Pole Spacing		Indicator		
ADJUSTABLE		BLACK MAGNETIC INK		
Results		Test Restrictions / Comments		
NO EVIDENCE OF SURFACE DEFECTS FOUND AT TIME OF EXAMINATION		NONE		
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:	Name, Address and qualifications of person who carried out the examination:	Name, Address of person signing the report on behalf of its author:	Reference Number
				1726161269
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industrial Estate Dyce Aberdeen AB21 0BF	Halliburton Forties Road Montrose DD10 9ET	M. YOUNGSON SNT LEVEL II COMPANY APPOINTED EXAMINER	STEWART GROVES UK OPERATIONS MANAGER	Customer Order Number
				51318
Signature of the person who carried out the examination		Signature on behalf of author for Hendrik Veder Group UK Ltd		
I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'				

 Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	NON DESTRUCT EXAMINATION REPORT		Report Number	1726161269/30B
			Date Of Report	07/05/2026
			Date Of Examination	07/05/2026
			Customer PO Number	51318
Job Description	Equipment Description		Serial Number(s)	
100% MPI CARRIED OUT ON ALL MASTER LINK / MASTER LINK ASSEMBLY WELDS	FOUR LEG WIRE ROPE SLING TO DNV2.7-1:2006 LEGS 7.8MTR X 28MM DIA IWRC GALV FITTED TO HA36QA QUAD ASSEMBLY **HA36QA**		BM-B-5506/1A	
Acceptance Standard			Heat Treatment Condition	
BSEN ISO 9934-1 : 2016			MORE THAN 24HOURS POST WELD	
Examination Procedure Number			MATERIAL	
WI4.1			STEEL CONSTRUCTION	
INSPECTION EQUIPMENT USED				
MAGNETIC PARTICLE				
Equipment Type		Contrast Paint		
Y6 YOKE ELECTROMAGNET		WHITE CONTRAST PAINT		
Pole Spacing		Indicator		
ADJUSTABLE		BLACK MAGNETIC INK		
Results		Test Restrictions / Comments		
NO EVIDENCE OF SURFACE DEFECTS FOUND AT TIME OF EXAMINATION		NONE		
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:	Name, Address and qualifications of person who carried out the examination:	Name, Address of person signing the report on behalf of its author:	Reference Number
				1726161269
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industrial Estate Dyce Aberdeen AB21 0BF	Halliburton Forties Road Montrose DD10 9ET	M. YOUNGSON SNT LEVEL II COMPANY APPOINTED EXAMINER	STEWART GROVES UK OPERATIONS MANAGER	Customer Order Number
				51318
Signature of the person who carried out the examination		Signature on behalf of author for Hendrik Veder Group UK Ltd		
I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'				