

July monthly Hendrik Veder Group Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	REPORT OF THOROUGH EXAMINATION (AND CERTIFICATE OF TEST IF APPLICABLE) The Lifting Operations and Lifting Equipment Regulations SI2307:1998 The Merchant Shipping and Vessels (Lifting Operations and Lifting Equipment) Regulations SI2148:2006 The Merchant Shipping and Fishing Vessels (Lifting Operations and Lifting Equipment)(Amendment) Regulations SI2166:2008						Report Number	1723160670/163
							Date Of Report	29/06/2023
							Date Of Examination	29/06/2023
							Customer PO Number	42662
Quantity & Description of Equipment	Manufacturer & Date Of Manufacture (if Known)	Working Load Limit	Proof Load Applied	First Examination YES / NO	Date of Last Thorough Examination	Date of Next Thorough Examination	Next Test Date	Test Certificate Number
MINI CONTAINER TO DNV 2.7-1 1.61M x 1.89M x 2.83M WELDED STEEL CONSTRUCTION 4 TOP CORNER LIFTING POINTS TARE WEIGHT: 1850 KGS GROSS WEIGHT: 7100 KGS	UNKNOWN	5250 KGS	N/A	NO	10/07/2014	29/12/2023	N/A	131635/76
FIVE LEG WIRE ROPE SLING ASSEMBLY TO DNV 2.7-1 4 LEGS 1.82M x 22mm DIA IWRC GALV CONNECTED VIA HA28QA QUAD ASSEMBLY 1 LEG 1.52M x 32mm DIA IWRC GALV TERM WITH HA32ML MASTERLINK	UNKNOWN	7.1 TONNE 0-45 DEG	N/A	NO	10/07/2014	29/12/2023	N/A	131635/76
SAFETY PIN BOW SHACKLES	UNKNOWN	6.5 TON	N/A	NO	10/07/2014	29/12/2023	N/A	131635/76
SERIAL NUMBER(S)	UNIT: BM-C-615 SLING: BM-C-615/1 SHACKLES: 615/A-D							
Particulars Of Defects which are a Danger to persons or 'None'	Particulars of any Defects or 'None'		Date by which other Defects are to be repaired		Particulars of any Repair, alterations to remedy Defect or 'None'		Particulars of any Observations	
NONE	NONE		N/A		NONE		N/A	
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:		Name, Address and qualifications of person who carried out the examination:		Name, Address of person signing the report on behalf of its author:		Reference Number	
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 0BF	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 0BF		M.YOUNGSON COMPANY APPOINTED EXAMINER		STEWART GROVES UK OPERATIONS MANAGER		1723160670	
							Customer Order Number	
							42662	
Signature of the person who carried out the examination			Signature on behalf of author for Hendrik Veder Group UK Ltd					
I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'								

 Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	NON DESTRUCT EXAMINATION REPORT		Report Number	1723160670/163A
			Date Of Report	29/06/2023
			Date Of Examination	29/06/2023
			Customer PO Number	42662
Job Description	Equipment Description		Serial Number(s)	
100% MPI CARRIED OUT ON ALL LIFT POINT WELDS	MINI CONTAINER TO DNV 2.7-1 1.61M x 1.89M x 2.83M WELDED STEEL CONSTRUCTION 4 TOP CORNER LIFTING POINTS TARE WEIGHT: 1850 KGS GROSS WEIGHT: 7100 KGS		BM-C-615	
Acceptance Standard			Heat Treatment Condition	
BSEN ISO 9934-1 : 2015			MORE THAN 24HOURS POST WELD	
Examination Procedure Number			MATERIAL	
WI4.1			STEEL CONSTRUCTION	
INSPECTION EQUIPMENT USED				
MAGNETIC PARTICLE				
Equipment Type		Contrast Paint		
Y6 YOKE ELECTROMAGNET		WHITE CONTRAST PAINT		
Pole Spacing		Indicator		
ADJUSTABLE		BLACK MAGNETIC INK		
Results		Test Restrictions / Comments		
NO EVIDENCE OF SURFACE DEFECTS FOUND AT TIME OF EXAMINATION		NONE		
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:	Name, Address and qualifications of person who carried out the examination:	Name, Address of person signing the report on behalf of its author:	Reference Number
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 0B	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 0B	M. YOUNGSON ASNT LEVEL II COMPANY APPOINTED EXAMINER	STEWART GROVES UK OPERATIONS MANAGER	1723160670
				Customer Order Number
				42466
Signature of the person who carried out the examination		Signature on behalf of author for Hendrik Veder Group UK Ltd		
I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'				

 Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	NON DESTRUCT EXAMINATION REPORT		Report Number	1723160670/163B
			Date Of Report	29/06/2023
			Date Of Examination	29/06/2023
			Customer PO Number	42662
Job Description	Equipment Description		Serial Number(s)	
100% MPI CARRIED OUT ON ALL MASTER LINK / MASTER LINK ASSEMBLY WELDS	FIVE LEG WIRE ROPE SLING ASSEMBLY TO DNV 2.7-1 4 LEGS 1.82M x 22mm DIA IWRC GALV CONNECTED VIA HA28QA QUAD ASSEMBLY 1 LEG 1.52M x 32mm DIA IWRC GALV TERM WITH HA32ML MASTERLINK ** HA28QA & HA32ML**		BM-C-615/1	
Acceptance Standard			Heat Treatment Condition	
BSEN ISO 9934-1 : 2015			MORE THAN 24HOURS POST WELD	
Examination Procedure Number			MATERIAL	
WI4.1			STEEL CONSTRUCTION	
INSPECTION EQUIPMENT USED				
MAGNETIC PARTICLE				
Equipment Type		Contrast Paint		
Y6 YOKE ELECTROMAGNET		WHITE CONTRAST PAINT		
Pole Spacing		Indicator		
ADJUSTABLE		BLACK MAGNETIC INK		
Results		Test Restrictions / Comments		
NO EVIDENCE OF SURFACE DEFECTS FOUND AT TIME OF EXAMINATION		NONE		
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:	Name, Address and qualifications of person who carried out the examination:	Name, Address of person signing the report on behalf of its author:	Reference Number
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 OB	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 OB	M. YOUNGSON ASNT LEVEL II COMPANY APPOINTED EXAMINER	STEWART GROVES UK OPERATIONS MANAGER	1723160670
				Customer Order Number
				42662
Signature of the person who carried out the examination		Signature on behalf of author for Hendrik Veder Group UK Ltd		
I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'				