

 Hendrik Veder Group Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	REPORT OF THOROUGH EXAMINATION (AND CERTIFICATE OF TEST IF APPLICABLE) The Lifting Operations and Lifting Equipment Regulations SI2307:1998 The Merchant Shipping and Vessels (Lifting Operations and Lifting Equipment) Regulations SI2148:2006 The Merchant Shipping and Fishing Vessels (Lifting Operations and Lifting Equipment)(Amendment) Regulations SI2166:2008						Report Number	1723161603/128
							Date Of Report	22/09/2023
							Date Of Examination	22/09/2023
							Customer PO Number	43416
Quantity & Description of Equipment	Manufacturer & Date Of Manufacture (if Known)	Working Load Limit	Proof Load Applied	First Examination YES / NO	Date of Last Thorough Examination	Date of Next Thorough Examination	Next Test Date	Test Certificate Number
10' OPEN TOP TO DNV 2.7-1 3M X 2.44M X 2.79M WELDED STEEL CONSTRUCTION 4 TOP CORNER LIFTING POINTS TARE WEIGHT: 2400 KGS GROSS WEIGHT: 12400 KGS	CONQ 13/12/2013 141563	10000 KGS	N/A	NO	14/06/2023	22/03/2024	N/A	1723160670/59
FOUR LEG WIRE ROPE SLING ASSEMBLY TO DNV 2.7-1 4 LEGS 3.5M X 26MM DIA IWRC GALV FITTED TO CROSBY A347 36MM QUAD ASSEMBLY	GLOBAL INTEGRATED 14/10/2013 91369/0017	12.4 TONNE 0-45°	N/A	NO	14/06/2023	22/03/2024	N/A	1723160670/59
SAFETY PIN BOW SHACKLES	UNKNOWN	8.5 TON	N/A	NO	14/06/2023	22/03/2024	N/A	1723160670/59
SERIAL NUMBER(S)	UNIT: BM-C-1074 SLING: BM-C-1074 SHACKLES: 1074/1A-1D							
Particulars Of Defects which are a Danger to persons or 'None'	Particulars of any Defects or 'None'		Date by which other Defects are to be repaired		Particulars of any Repair, alterations to remedy Defect or 'None'		Particulars of any Observations	
NONE	NONE		N/A		NONE		N/A	
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:		Name, Address and qualifications of person who carried out the examination:		Name, Address of person signing the report on behalf of its author:		Reference Number	
							1723161603	
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 0BF	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 0BF		SEBASTIAN GACH COMPANY APPOINTED EXAMINER		STEWART GROVES UK OPERATIONS MANAGER		Customer Order Number	
							43416	
Signature of the person who carried out the examination			Signature on behalf of author for Hendrik Veder Group UK Ltd					

I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'

 Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	NON DESTRUCT EXAMINATION REPORT		Report Number	1723161603/128A
			Date Of Report	22/09/2023
			Date Of Examination	22/09/2023
			Customer PO Number	43416
Job Description	Equipment Description		Serial Number(s)	
100% MPI CARRIED OUT ON ALL LIFT POINT WELDS	10' OPEN TOP TO DNV 2.7-1 3M X 2.44M X 2.79M WELDED STEEL CONSTRUCTION 4 TOP CORNER LIFTING POINTS TARE WEIGHT: 2400 KGS GROSS WEIGHT: 12400 KGS		BM-C-1074	
Acceptance Standard			Heat Treatment Condition	
BSEN ISO 9934-1 : 2015			MORE THAN 24HOURS POST WELD	
Examination Procedure Number			MATERIAL	
WI4.1			STEEL CONSTRUCTION	
INSPECTION EQUIPMENT USED				
MAGNETIC PARTICLE				
Equipment Type		Contrast Paint		
Y6 YOKE ELECTROMAGNET		WHITE CONTRAST PAINT		
Pole Spacing		Indicator		
ADJUSTABLE		BLACK MAGNETIC INK		
Results		Test Restrictions / Comments		
NO EVIDENCE OF SURFACE DEFECTS FOUND AT TIME OF EXAMINATION		NONE		
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:	Name, Address and qualifications of person who carried out the examination:	Name, Address of person signing the report on behalf of its author:	Reference Number
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 0B	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 0B	SEBASTIAN GACH PCN LEVEL 2D COMPANY APPOINTED EXAMINER	STEWART GROVES UK OPERATIONS MANAGER	1723161603
				Customer Order Number
				43416
Signature of the person who carried out the examination		Signature on behalf of author for Hendrik Veder Group UK Ltd		
I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'				

 Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	NON DESTRUCT EXAMINATION REPORT		Report Number	1723161603/128B
			Date Of Report	22/09/2023
			Date Of Examination	22/09/2023
			Customer PO Number	43416
Job Description	Equipment Description		Serial Number(s)	
100% MPI CARRIED OUT ON ALL MASTER LINK / MASTER LINK ASSEMBLY WELDS	FOUR LEG WIRE ROPE SLING ASSEMBLY TO DNV 2.7-1 4 LEGS 3.5M X 26MM DIA IWRC GALV FITTED TO CROSBY A347 36MM QUAD ASSEMBLY ** CROSBY A347 36MM**		BM-C-1074	
Acceptance Standard			Heat Treatment Condition	
BSEN ISO 9934-1 : 2015			MORE THAN 24HOURS POST WELD	
Examination Procedure Number			MATERIAL	
WI4.1			STEEL CONSTRUCTION	
INSPECTION EQUIPMENT USED				
MAGNETIC PARTICLE				
Equipment Type		Contrast Paint		
Y6 YOKE ELECTROMAGNET		WHITE CONTRAST PAINT		
Pole Spacing		Indicator		
ADJUSTABLE		BLACK MAGNETIC INK		
Results		Test Restrictions / Comments		
NO EVIDENCE OF SURFACE DEFECTS FOUND AT TIME OF EXAMINATION		NONE		
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:	Name, Address and qualifications of person who carried out the examination:	Name, Address of person signing the report on behalf of its author:	Reference Number
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 0B	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 0B	SEBASTIAN GACH PCN LEVEL 2D COMPANY APPOINTED EXAMINER	STEWART GROVES UK OPERATIONS MANAGER	1723161603
				Customer Order Number
				43416
Signature of the person who carried out the examination		Signature on behalf of author for Hendrik Veder Group UK Ltd		
I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'				