

 Hendrik Veder Group Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	REPORT OF THOROUGH EXAMINATION (AND CERTIFICATE OF TEST IF APPLICABLE) The Lifting Operations and Lifting Equipment Regulations SI2307:1998 The Merchant Shipping and Vessels (Lifting Operations and Lifting Equipment) Regulations SI2148:2006 The Merchant Shipping and Fishing Vessels (Lifting Operations and Lifting Equipment)(Amendment) Regulations SI2166:2008						Report Number	1725160910/177
							Date Of Report	30/04/2025
							Date Of Examination	30/04/2025
							Customer PO Number	48338
Quantity & Description of Equipment	Manufacturer & Date Of Manufacture (if Known)	Working Load Limit	Proof Load Applied	First Examination YES / NO	Date of Last Thorough Examination	Date of Next Thorough Examination	Next Test Date	Test Certificate Number
OFFSHORE MINI CONTAINER TO DNV2.7-1/BS EN 12079 C/W INTERNAL SHELF 1.60M X 1.88M X 2.82M APPROX ALL WELDED STEEL CONSTRUCTION 4 TOP CORNER MOUNTED LIFTING POINTS TARE WEIGHT: 1850 KGS GROSS WEIGHT: 7100 KGS	CONQ SP ZOO 11/2013 141577	5250 KGS 2000 KGS INTERNAL SHELF	N/A	NO	25/11/2024	30/04/2026 EXAMINED IN ACCORDANCE WITH DNV2.7-1	N/A	1724162722/112
FIVE LEG WIRE ROPE SLING ASSY TO DNV2.7-1:2006 TOP LEG 1.31M X 32MM DIA IWRC GALV FITTED TO A344 28MM MASTER LINK BOTTOM LEGS 1.72M X 22MM DIA IWRC GALV FITTED TO A347 31MM QUAD ASSEMBLY	G.L.S.LTD 91369/0002 14/10/2013	7.1 TONNE 0-45 DEG	N/A	NO	25/11/2024	30/04/2026	N/A	1724162722/112
SAFETY PIN BOW SHACKLES-9NE 1NF	CROSBY	6.5 TON	N/A	NO	25/11/2024	30/04/2026	N/A	1724162722/112
SERIAL NUMBER(S)	UNIT BM-C-664 SLING BM-C-664/1 SHACKLES 664/1A-1D							
Particulars Of Defects which are a Danger to persons or 'None'	Particulars of any Defects or 'None'		Date by which other Defects are to be repaired		Particulars of any Repair, alterations to remedy Defect or 'None'		Particulars of any Observations	
NONE	NONE		N/A		NONE		N/A	
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:		Name, Address and qualifications of person who carried out the examination:		Name, Address of person signing the report on behalf of its author:		Reference Number	
							1725160910	
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 0BF	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 0BF		SEBASTIAN GACH COMPANY APPOINTED EXAMINER		STEWART GROVES UK OPERATIONS MANAGER		Customer Order Number	
							48338	
Signature of the person who carried out the examination			Signature on behalf of author for Hendrik Veder Group UK Ltd					

I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'

 Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	NON DESTRUCT EXAMINATION REPORT		Report Number	1725160910/177A
			Date Of Report	30/04/2025
			Date Of Examination	30/04/2025
			Customer PO Number	48338
Job Description	Equipment Description		Serial Number(s)	
100% MPI CARRIED OUT ON ALL LIFT POINT WELDS	OFFSHORE MINI CONTAINER TO DNV2.7-1/BS EN 12079 C/W INTERNAL SHELF 1.60M X 1.88M X 2.82M APPROX ALL WELDED STEEL CONSTRUCTION 4 TOP CORNER MOUNTED LIFTING POINTS TARE WEIGHT: 1850 KGS GROSS WEIGHT: 7100 KGS		BM-C-664	
Acceptance Standard			Heat Treatment Condition	
BSEN ISO 9934-1 : 2016			MORE THAN 24HOURS POST WELD	
Examination Procedure Number			MATERIAL	
WI4.1			STEEL CONSTRUCTION	
INSPECTION EQUIPMENT USED				
MAGNETIC PARTICLE				
Equipment Type		Contrast Paint		
Y6 YOKE ELECTROMAGNET		WHITE CONTRAST PAINT		
Pole Spacing		Indicator		
ADJUSTABLE		BLACK MAGNETIC INK		
Results		Test Restrictions / Comments		
NO EVIDENCE OF SURFACE DEFECTS FOUND AT TIME OF EXAMINATION		NONE		
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:	Name, Address and qualifications of person who carried out the examination:	Name, Address of person signing the report on behalf of its author:	Reference Number
				1725160910
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 OB	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 OB	SEBASTIAN GACH PCN LEVEL 2D COMPANY APPOINTED EXAMINER	STEWART GROVES UK OPERATIONS MANAGER	Customer Order Number
				48338
Signature of the person who carried out the examination		Signature on behalf of author for Hendrik Veder Group UK Ltd		
I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'				

 Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	NON DESTRUCT EXAMINATION REPORT		Report Number	1725160910/177B
			Date Of Report	30/04/2025
			Date Of Examination	30/04/2025
			Customer PO Number	48338
Job Description	Equipment Description		Serial Number(s)	
100% MPI CARRIED OUT ON ALL MASTER LINK / MASTER LINK ASSEMBLY WELDS	FIVE LEG WIRE ROPE SLING ASSY TO DNV2.7-1:2006 TOP LEG 1.31M X 32MM DIA IWRC GALV FITTED TO A344 28MM MASTER LINK BOTTOM LEGS 1.72M X 22MM DIA IWRC GALV FITTED TO A347 31MM QUAD ASSEMBLY ** A344 28mm & A347 31mm**		BM-C-664/1	
Acceptance Standard			Heat Treatment Condition	
BSEN ISO 9934-1 : 2016			MORE THAN 24HOURS POST WELD	
Examination Procedure Number			MATERIAL	
WI4.1			STEEL CONSTRUCTION	
INSPECTION EQUIPMENT USED				
MAGNETIC PARTICLE				
Equipment Type		Contrast Paint		
Y6 YOKE ELECTROMAGNET		WHITE CONTRAST PAINT		
Pole Spacing		Indicator		
ADJUSTABLE		BLACK MAGNETIC INK		
Results		Test Restrictions / Comments		
NO EVIDENCE OF SURFACE DEFECTS FOUND AT TIME OF EXAMINATION		NONE		
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:	Name, Address and qualifications of person who carried out the examination:	Name, Address of person signing the report on behalf of its author:	Reference Number
				1725160910
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 OB	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 OB	SEBASTIAN GACH PCN LEVEL 2D COMPANY APPOINTED EXAMINER	STEWART GROVES UK OPERATIONS MANAGER	Customer Order Number
				48338
Signature of the person who carried out the examination		Signature on behalf of author for Hendrik Veder Group UK Ltd		
I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'				