

 Hendrik Veder Group Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	REPORT OF THOROUGH EXAMINATION (AND CERTIFICATE OF TEST IF APPLICABLE) The Lifting Operations and Lifting Equipment Regulations SI2307:1998 The Merchant Shipping and Vessels (Lifting Operations and Lifting Equipment) Regulations SI2148:2006 The Merchant Shipping and Fishing Vessels (Lifting Operations and Lifting Equipment)(Amendment) Regulations SI2166:2008						Report Number	1725161218/111
							Date Of Report	21/05/2025
							Date Of Examination	21/05/2025
							Customer PO Number	48599
Quantity & Description of Equipment	Manufacturer & Date Of Manufacture (if Known)	Working Load Limit	Proof Load Applied	First Examination YES / NO	Date of Last Thorough Examination	Date of Next Thorough Examination	Next Test Date	Test Certificate Number
OFFSHORE CONTAINER TO DNV2.7-1 2.45M X 1.66M X 2.41M WELDED STEEL CONSTRUCTION 4 TOP MOUNTED LIFTING POINTS TARE WEIGHT: 2000 KGS GROSS WEIGHT: 8000 KGS FIVE LEG WIRE ROPE SLING TO DNV2.7-1:2006 TOP LEG 1.32MTR X 32MM DIA IWRC GALV FITTED TO HA32ML MASTER LINK BOTTOM LEGS 2.1MTR X 24MM DIA IWRC GALV FITTED TO A347 31MM MASTER LINK ASSEMBLY G2130 SAFETY PIN BOW SHACKLE	BLUE MANTA 67792 07/2007 HENDRIK VEDER 2308461-1723161458/01 17/08/2023	6000 KGS	N/A	NO	02/04/2025	21/11/2025	N/A	1725160910/11
		8 TONNE @0-45°	N/A	NO	02/04/2025	21/11/2025	N/A	1725160910/11
	CROSBY	6.5 TONNE	N/A	NO	02/04/2025	21/11/2025	N/A	1725160910/11
SERIAL NUMBER(S)	UNIT BM-C-8504 SLING BM-C-8504/1 SHACKLES 4/2-5							
Particulars Of Defects which are a Danger to persons or 'None'	Particulars of any Defects or 'None'		Date by which other Defects are to be repaired		Particulars of any Repair, alterations to remedy Defect or 'None'		Particulars of any Observations	
NONE	NONE		N/A		NONE		N/A	
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:		Name, Address and qualifications of person who carried out the examination:		Name, Address of person signing the report on behalf of its author:		Reference Number	
							1725161218	
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 0BF	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 0BF		S. GACH COMPANY APPOINTED EXAMINER		STEWART GROVES UK OPERATIONS MANAGER		Customer Order Number	
							48599	
Signature of the person who carried out the examination			Signature on behalf of author for Hendrik Veder Group UK Ltd					
I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'								

 Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	NON DESTRUCT EXAMINATION REPORT		Report Number	1725161218/111A
			Date Of Report	21/05/2025
			Date Of Examination	21/05/2025
			Customer PO Number	48599
Job Description	Equipment Description		Serial Number(s)	
100% MPI CARRIED OUT ON ALL LIFT POINT WELDS	OFFSHORE CONTAINER TO DNV2.7-1 2.45M X 1.66M X 2.41M WELDED STEEL CONSTRUCTION 4 TOP MOUNTED LIFTING POINTS TARE WEIGHT: 2000 KGS GROSS WEIGHT: 8000 KGS		BM-C-8504	
Acceptance Standard			Heat Treatment Condition	
BSEN ISO 9934-1 : 2016			MORE THAN 24HOURS POST WELD	
Examination Procedure Number			MATERIAL	
WI4.1			STEEL CONSTRUCTION	
INSPECTION EQUIPMENT USED				
MAGNETIC PARTICLE				
Equipment Type		Contrast Paint		
Y6 YOKE ELECTROMAGNET		WHITE CONTRAST PAINT		
Pole Spacing		Indicator		
ADJUSTABLE		BLACK MAGNETIC INK		
Results		Test Restrictions / Comments		
NO EVIDENCE OF SURFACE DEFECTS FOUND AT TIME OF EXAMINATION		NONE		
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:	Name, Address and qualifications of person who carried out the examination:	Name, Address of person signing the report on behalf of its author:	Reference Number
				1725161218
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 OB	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 OB	SEBASTIAN GACH PCN LEVEL 2D COMPANY APPOINTED EXAMINER	STEWART GROVES UK OPERATIONS MANAGER	Customer Order Number
				48599
Signature of the person who carried out the examination		Signature on behalf of author for Hendrik Veder Group UK Ltd		
I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'				

 Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	NON DESTRUCT EXAMINATION REPORT		Report Number	1725161218/111B
			Date Of Report	21/05/2025
			Date Of Examination	21/05/2025
			Customer PO Number	48599
Job Description	Equipment Description		Serial Number(s)	
100% MPI CARRIED OUT ON ALL MASTER LINKS SURFACES	FIVE LEG WIRE ROPE SLING TO DNV2.7-1:2006 TOP LEG 1.32MTR X 32MM DIA IWRC GALV FITTED TO HA32ML MASTER LINK BOTTOM LEGS 2.1MTR X 24MM DIA IWRC GALV FITTED TO A347 31MM MASTER LINK ASSEMBLY ** HA32ML & A347 31MM **		BM-C-8504/1	
Acceptance Standard			Heat Treatment Condition	
BSEN ISO 9934-1 : 2016			MORE THAN 24HOURS POST WELD	
Examination Procedure Number			MATERIAL	
WI4.1			STEEL CONSTRUCTION	
INSPECTION EQUIPMENT USED				
MAGNETIC PARTICLE				
Equipment Type		Contrast Paint		
Y6 YOKE ELECTROMAGNET		WHITE CONTRAST PAINT		
Pole Spacing		Indicator		
ADJUSTABLE		BLACK MAGNETIC INK		
Results		Test Restrictions / Comments		
NO EVIDENCE OF SURFACE DEFECTS FOUND AT TIME OF EXAMINATION		NONE		
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:	Name, Address and qualifications of person who carried out the examination:	Name, Address of person signing the report on behalf of its author:	Reference Number
				1725161218
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 OB	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 OB	SEBASTIAN GACH PCN LEVEL 2D COMPANY APPOINTED EXAMINER	STEWART GROVES UK OPERATIONS MANAGER	Customer Order Number
				48599
Signature of the person who carried out the examination		Signature on behalf of author for Hendrik Veder Group UK Ltd		
I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'				