



 Hendrik Veder Group Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	REPORT OF THOROUGH EXAMINATION (AND CERTIFICATE OF TEST IF APPLICABLE) The Lifting Operations and Lifting Equipment Regulations SI2307:1998 The Merchant Shipping and Vessels (Lifting Operations and Lifting Equipment) Regulations SI2148:2006 The Merchant Shipping and Fishing Vessels (Lifting Operations and Lifting Equipment)(Amendment) Regulations SI2166:2008						Report Number	1724161255/24
							Date Of Report	06/06/2024
							Date Of Examination	06/06/2024
							Customer PO Number	45666
Quantity & Description of Equipment	Manufacturer & Date Of Manufacture (if Known)	Working Load Limit	Proof Load Applied	First Examination YES / NO	Date of Last Thorough Examination	Date of Next Thorough Examination	Next Test Date	Test Certificate Number
TOOL BOX TO DNV2.7-1 & BSEN12079 1.37M X 0.87M X 1.36M APPROX ALL WELDED STEEL CONSTRUCTION C/W 4 TOP MOUNTED LIFTING POINTS TARE WEIGHT: 400 KGS GROSS WEIGHT: 1000 KGS	ABERDEEN LIFTING 22/12/2016 H7827-02	600 KGS	N/A	NO	12/04/2024	06/12/2024	N/A	1724160632/51
FOUR LEG WIRE ROPE SLING TO DNV-ST-E271:2023 4 LEGS 1.2MTR X 18MM DIA IWRC GALV FITTED TO HA25QA MASTER LINK ASSEMBLY	HENDRIK VEDER 12/04/2024 2404302	1 TONNE 0-45°	N/A	NO	12/04/2024	06/12/2024	N/A	2404302
G-2130 SAFETY PIN BOW SHACKLES	CROSBY CC7-2024032600313	4.75 TONNE	N/A	NO	12/04/2024	06/12/2024	N/A	2404302
SERIAL NUMBER(S)	UNIT: BM-CPT-02 SLING: BM-CPT-02/1 SHACKLES: 02/1A-1D							
Particulars Of Defects which are a Danger to persons or 'None'	Particulars of any Defects or 'None'		Date by which other Defects are to be repaired		Particulars of any Repair, alterations to remedy Defect or 'None'		Particulars of any Observations	
NONE	NONE		N/A		NONE		N/A	
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:		Name, Address and qualifications of person who carried out the examination:		Name, Address of person signing the report on behalf of its author:		Reference Number	
							1724161255	
							Customer Order Number	
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 OBF	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 OBF		G. MACKAY COMPANY APPOINTED EXAMINER		STEWART GROVES UK OPERATIONS MANAGER		45666	
Signature of the person who carried out the examination			Signature on behalf of author for Hendrik Veder Group UK Ltd					
I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'								

 Hendrik Veder Group UK Limited Unit 6-7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel : +44(0)1224 894949	NON DESTRUCT EXAMINATION REPORT		Report Number	1724161255/24A
			Date Of Report	06/06/2024
			Date Of Examination	06/06/2024
			Customer PO Number	45666
Job Description	Equipment Description		Serial Number(s)	
100% MPI CARRIED OUT ON ALL LIFT POINT WELDS	TOOL BOX TO DNV2.7-1 & BSEN12079 1.37M X 0.87M X 1.36M APPROX ALL WELDED STEEL CONSTRUCTION C/W 4 TOP MOUNTED LIFTING POINTS TARE WEIGHT: 400 KGS GROSS WEIGHT: 1000 KGS		BM-CPT-02	
Acceptance Standard			Heat Treatment Condition	
BSEN ISO 9934-1 : 2016			MORE THAN 24HOURS POST WELD	
Examination Procedure Number			MATERIAL	
WI4.1			STEEL CONSTRUCTION	
INSPECTION EQUIPMENT USED				
MAGNETIC PARTICLE				
Equipment Type		Contrast Paint		
Y6 YOKE ELECTROMAGNET		WHITE CONTRAST PAINT		
Pole Spacing		Indicator		
ADJUSTABLE		BLACK MAGNETIC INK		
Results		Test Restrictions / Comments		
NO EVIDENCE OF SURFACE DEFECTS FOUND AT TIME OF EXAMINATION		NONE		
Name & Address of Employer for whom the Thorough Examination was made:	Address of premises at which the examination was carried out:	Name, Address and qualifications of person who carried out the examination:	Name, Address of person signing the report on behalf of its author:	Reference Number
Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 OB	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industriel Estate Dyce Aberdeen AB21 OB	G. MACKAY PCN LEVEL 2D COMPANY APPOINTED EXAMINER	STEWART GROVES UK OPERATIONS MANAGER	1724161255
				Customer Order Number
				45666
Signature of the person who carried out the examination		Signature on behalf of author for Hendrik Veder Group UK Ltd		
I hereby certify on the above stated date the item(s) described above were Thoroughly Examined, and as far as reasonably practicable by this type of termination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'				