

ABERDEEN LIFTING SERVICES LTD

CERTIFICATE OF TEST, EXAMINATION AND INSPECTION REPORT

Provision and use of Work Equipment Regulations-SI 2306

Lifting Operations and Lifting Equipment Regulations- SI 2307

CLIENT:	BLUE MANTA 6 KIRKTON AVENUE PITMEDDEN RD IND EST DYCE ABERDEEN AB21 0BF	TEST HOUSE:	ABERDEEN LIFTING SERVICES LTD UNITS 2,3&4 WOODLANDS ROAD KIRKHILL INDUSTRIAL ESTATE, DYCE ABERDEEN AB21 0GX TEL: 01224 723333 FAX: 01224 723311
P.O. NO:	9241	REQUISITION NO:	
CERT NO:	C7647-01	INSPECTION DATE:	15/12/2011


SERIAL NO:	QTY	DESCRIPTION	SWL/PAYLOAD	PROOF LOAD
BM-SP-5007	1	50" SPOOLER TO BSEN12079 & DNV2.7-1 1.98M x 1.53M x 1.81M APPROX ALL WELDED STEEL CONSTRUCTION 4 TOP MOUNTED LIFTING POINTS TARE WT: 1200 KGS GROSS WT: 6200 KGS 4 POINT LIFT TEST	5000 KGS	15500 KGS
BM-SP-5007/1	1	4 LEG WIRE ROPE SLING TO DNV2.7-1 (2006) LEGS 2.00M x 22MM DIA IWRC FITTED TO CROSBY 31 QUAD ASSY	WLL 6.2 TONNE 0-45 DEG	12.4 TONNE PER LEG
07/2-5	4	SAFETY PIN BOW SHACKLES	6.5 TON	13 TON

M.P.I INSPECTION DETAILS

PROCEDURE:	ALNDT.01A REV 01	EQUIPMENT:	Y6 YOKE	METHOD:	WET CONTINOUS
SPECIFICATION:	ASTME1444/E1444 M-11	MEDIA:	NPT 16 WHITE PAINT	INSPECTOR:	D.CRAIG
MATERIAL:	WELDED CARBON STEEL	INDICATOR:	BLACK INK	QUALS:	SNT 11

RESULTS: A MAGNETIC PARTICLE INSPECTION WAS CARRIED OUT ON LIFTING POINT WELDMENTS. ON THE EQUIPMENT NO CRACK OR CRACKLIKE INDICATIONS WERE NOTED AT TIME OF INSPECTION.

DECLARATION: I HEREBY DECLARE THAT THE ABOVE INFORMATION IS CORRECT AND THE EQUIPMENT HAS BEEN TESTED AND THOROUGHLY EXAMINED IN ACCORDANCE WITH THE APPROPRIATE PROVISIONS AND IS FREE FROM DEFECTS AFFECTING SAFETY.

	COMPLETED BY
ENGINEER	D.CRAIG
SIGNATURE	
DATE	15/12/2011

NEXT INSPECTION DATE: 14/06/2012
DATE OF MANUFACTURE: DECEMBER 2011



ABERDEEN LIFTING SERVICES LTD

MAGNETIC PARTICLE INSPECTION REPORT

CUSTOMER: BLUE MANTA	LOCATION: ALS YARD
P.O. No: 9241	CERT No: C7647-02
JOB No:	DATE OF INSP: 15/12/2011

JOB DESCRIPTION:

100% MAGNETIC PARTICLE INSPECTION CARRIED OUT PRE&POST LOAD TEST ON ALL LOAD BEARING WELDS AND 20% SECONDARY WELDS

ITEM: 50" SPOOLER	
QUANTITY: 1	SURFACE: AS WELDED
SERIAL No: BM-SP-5007	EQUIPMENT: Y6 YOKE
DRG No: N/A	MEDIA: NPT 16 WHITE PAINT
MATERIAL: CARBON STEEL	INDICATOR: BLACK INK
PROCEDURE: ALNDT.01A REV 01	METHOD: WET CONTINUOUS
SPECIFICATION: ASTM E1444/E1444M-11	

RESULTS: NO CRACK OR CRACKLIKE INDICATIONS ARE NOTED AT TIME OF INSPECTION.

	COMPLETED BY
ENGINEER/TECHNICIAN	D.CRAIG
SIGNATURE	<i>PP. YH e Craig</i>
DATE	15/12/2011