



UNIVERSAL INSPECTION (UK) LTD
Certificate of Visual Examination and Inspection Report SI 2306 SI 2307

Client:	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industrial Estate Dyce Aberdeen AB21 0BF	Test House:	Universal Inspection (UK) Ltd Greenwell Road East Tullos Aberdeen AB12 3AX Tel: 01224 894949 Fax: 01224 898844
P.O. No:	32139	Requisition No:	139899
Cert No:	139899/51	Inspection Date:	08/08/2019

Serial no:	Qty	Description	SWL/WLL
BM-SP-7506	01	SPOOLER FRAME IN ACCORDANCE WITH DNV 2.7-1 2M x 2M x 2.30M WELDED STEEL CONSTRUCTION 4 TOP CORNER LIFTING POINTS TARE WEIGHT: 3000 KGS GROSS WEIGHT: 11000 KGS	8000 KGS
BM-SP-7521/1	01	FOUR LEG WIRE ROPE SLING ASSEMBLY TO DNV 2.7-1 4 LEGS 3.2M x 26mm DIA IWRC GALV CONNECTED VIA CROSBY A347 31mm QUAD ASSEMBLY	11 TONNE 0-45 DEG
21/2-5	04	SAFETY PIN BOW POLAR SHACKLES	8.5 TON

Previous Test Details

Unit:	VISUAL	Tested by:	U.I.L.	Cert No.	138732/134	Date:	30/01/2019
Sling:	VISUAL	Tested by:	U.I.L.	Cert No.	138732/134	Date:	30/01/2019

MPI/DPI Inspection Details

Procedure:	QP09:02	Equipment:	Y6 YOKE	Method:	Continuous
Specification:	AWS D1:1	Media:	White Paint	Inspector:	M. YOUNGSON
Material:	Carbon Steel	Indicator:	Black Ink	Quals:	ASNT II
Items Inspected:	Welded Pad Eyes	Quantity:	Four	Results:	Fit For Use

Declaration: I hereby declare that the above information is correct and the equipment has been thoroughly examined in accordance with the appropriate provisions and is free from defects affecting safety.

	COMPLETED BY	APPROVED BY	ACCEPTED BY
ENGINEER	M. YOUNGSON	N. TRAVIS	<i>J. Patterson</i>
SIGNATURE	<i>[Signature]</i>	<i>[Signature]</i>	<i>[Signature]</i>
DATE	08/08/2019	08/08/2019	09/08/2019





UNIVERSAL INSPECTION (UK) LIMITED

GREENWELL ROAD, EAST TULLOS, ABERDEEN AB12 3AX

TELEPHONE: 01224 894949 FAX: 01224 898844

Magnetic Particle Inspection Report

Customer:	BLUE MANTA INTERNATIONAL LTD	Location:	BLUE MANTA
P.O. No:	32139	Report No:	139899/51A
Job No:	139899	Date of Insp:	08/08/2019

Item:	QUAD ASSEMBLY		
Quantity:	ONE	Surface:	AS WELDED
Sling I.D.:	BM-SP-7521/1	Equipment:	Y6 YOKE ELECTROMAGNET
Size:	CROSBY A347 31mm	Serial No:	5561
Drg. No:	N/A	Technique:	CONTINUOUS
Material:	CARBON STEEL	Background:	WHITE CONTRAST
Client:	BLUE MANTA	Exam:	BLACK INK
Procedure:	QP09:02	Flux Ind:	CASTROL STRIP
Specification:	AWS D1:1		



Results:

A 100% MAGNETIC PARTICLE INSPECTION WAS CARRIED OUT ON THE BUTT WELD OF THE QUAD ASSEMBLY FITTED TO THE ABOVE NOTED SLING ASSEMBLY

NO EVIDENCE OF SURFACE DEFECTS WERE NOTED AT THE TIME OF INSPECTION

ACCEPTABLE TO SPECIFICATION

Sketch Included: ~~YES~~/ NO

	COMPLETED BY	APPROVED BY	ACCEPTED BY
ENGINEER/TECHNICIAN	M. YOUNGSON	N. TRAVIS	
SIGNATURE			
DATE	08/08/2019	08/08/2019	

