

ABERDEEN LIFTING SERVICES LTD

CERTIFICATE OF TEST, EXAMINATION, AND INSPECTION REPORT

Provision and use of Work Equipment Regulations-SI 2306

Lifting Operations and Lifting Equipment Regulations- SI 2307



CLIENT:	BLUE MANTA 6 KIRKTON AVENUE PITMEDDEN RD IND EST DYCE ABERDEEN AB21 0BF	TEST HOUSE:	ABERDEEN LIFTING SERVICES LTD HOWE MOSS CRESCENT KIRKHILL INDUSTRIAL ESTATE, DYCE ABERDEEN AB21 0GN TEL: 01224 723333 FAX: 01224 723311
P.O. NO:	48934	REQUISITION NO:	
CERT NO:	ALS16429-01	INSPECTION DATE:	04/06/2025


SERIAL NO:	QTY	DESCRIPTION	SWL/PAYLOAD	PROOF LOAD
BM-SP-4045	1	40" SPOOLER TO DNV 2.7-1, LRCCS & ISO10855 1.67M x 1.37M x 1.60M APPROX ALL WELDED STEEL CONSTRUCTION C/W 4 TOP INNER CORNER MOUNTED LIFTING POINTS TARE WT: 1000 KGS GROSS WT: 4500 KGS 4 POINT TEST	3500 KGS	11250 KGS

M.P.I INSPECTION DETAILS

PROCEDURE:	WI ALNDT.01A REV05	EQUIPMENT:	Y6 YOKE (2208106)	METHOD:	WET CONTINUOUS
SPECIFICATION:	ASTM E1444/E144M-16e1 & BSEN ISO 23278:2015 & BSEN ISO 17638:2016	MEDIA:	NPT 16 WHITE PAINT	INSPECTOR:	G. WOOD
MATERIAL:	WELDED CARBON STEEL	INDICATOR:	BLACK INK	QUALS:	PCN II

RESULTS: A MAGNETIC PARTICLE INSPECTION WAS CARRIED OUT ON LIFTING POINT WELDMENTS. ON THE EQUIPMENT NO CRACK OR CRACKLIKE INDICATIONS WERE NOTED AT TIME OF INSPECTION.

DECLARATION: I HEREBY DECLARE THAT THE ABOVE INFORMATION IS CORRECT AND THE EQUIPMENT HAS BEEN TESTED AND THOROUGHLY EXAMINED IN ACCORDANCE WITH THE APPROPRIATE PROVISIONS AND IS FREE FROM DEFECTS AFFECTING SAFETY.

	COMPLETED BY
ENGINEER	G. WOOD
SIGNATURE	
DATE	04/06/2025

NEXT INSPECTION DATE: 03/12/2025
DATE OF MANUFACTURE: 06/2025

ABERDEEN LIFTING SERVICES LTD



MAGNETIC PARTICLE INSPECTION REPORT

CUSTOMER: BLUE MANTA	LOCATION: ALS YARD
P.O. No: 48934	CERT No: ALS16429-02
JOB No:	DATE OF INSP: 04/06/2025

JOB DESCRIPTION:

100% MAGNETIC PARTICLE INSPECTION CARRIED OUT PRE & POST LOAD TEST ON ALL LOAD BEARING WELDS AND 20% SECONDARY WELDS

ITEM: 40" SPOOLER	
QUANTITY: 1	SURFACE: AS WELDED
SERIAL No: BM-SP-4045	EQUIPMENT: Y6 YOKE (2208106)
DRG. No: N/A	MEDIA: NPT 16 WHITE PAINT
MATERIAL: CARBON STEEL	INDICATOR: BLACK INK
PROCEDURE: WI ALNDT.01A REV 05	METHOD: WET CONTINUOUS
SPECIFICATION: ASTM E1444/E144M-16e1, BSEN ISO 23278:2015, BSEN ISO 17638:2016	QUALIFICATIONS: PCN II

RESULTS: NO CRACK OR CRACKLIKE INDICATIONS ARE NOTED AT TIME OF INSPECTION.

	COMPLETED BY
ENGINEER/TECHNICIAN	G. WOOD
SIGNATURE	
DATE	04/06/2025