



UNIVERSAL INSPECTION (UK) LTD

Certificate of Visual Examination and Inspection Report SI 2306 SI 2307

Client:	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industrial Estate Dyce Aberdeen AB21 0BF	Test House:	Universal Inspection (UK) Ltd Greenwell Road East Tullos Aberdeen AB12 3AX Tel: 01224 894949 Fax: 01224 898844
P.O. No:	27057	Requisition No:	136701
Cert No:	136701/61	Inspection Date:	10/10/2017

Serial no:	Qty	Description	SWL/WLL
BM-SW-0459	01	SHEAVE WHEEL TESTED IN ACCORDANCE WITH DNV 2.22 AND LRS CODE L.A.M.E CH3 FITTED WITH CENTRAL LIFT POINT	2 TONNE LINE PULL 4 TONNE HEAD FITTING
59/1	01	SAFETY PIN BOW SHACKLE (LOAD PIN)	9.5 TON
59/2	01	SAFETY PIN BOW SHACKLE	2 TON
59/3	01	¾" G402 REGULAR SWIVEL	4.54 TONNE

Previous Test Details

Sheave:	VISUAL	Tested by:	U.I.L.	Cert No.	134499/78	Date:	17/06/2016
Swivel:	VISUAL	Tested by:	U.I.L.	Cert No.	134499/78	Date:	17/06/2016

MPI/DPI Inspection Details

Procedure:	QP09:02	Equipment:	Y6 YOKE	Method:	Continuous
Specification:	AWS D1:1	Media:	White Paint	Inspector:	D. REZIN
Material:	Carbon Steel	Indicator:	Black Ink	Quals:	ASNT II

Declaration: I hereby declare that the above information is correct and the equipment has been thoroughly examined in accordance with the appropriate provisions and is free from defects affecting safety.

	COMPLETED BY	APPROVED BY	ACCEPTED BY
ENGINEER	D. REZIN	N. TRAVIS	
SIGNATURE			
DATE	10/10/2017	10/10/2017	

