



UNIVERSAL INSPECTION (UK) LTD
Certificate of Visual Examination and Inspection Report SI 2306 SI 2307

Client:	Blue Manta International Ltd 5 Kirkton Avenue Pitmedden Road Industrial Estate Dyce Aberdeen AB21 0BF	Test House:	Universal Inspection (UK) Ltd Unit 6/7 Woodside Road Bridge of Don Aberdeen AB23 8EF Tel: 01224 894949
P.O. No:	34459	Requisition No:	140917
Cert No:	140917/19	Inspection Date:	06/05/2020

Serial no:	Qty	Description	SWL/WLL
BM-SWX-1004	01	SHEAVE WHEEL TESTED TO DNV 2.22 FITTED WITH 2 No TOP LIFTING POINTS	5 TONNE LINE PULL 10 TONNE HEAD FITTING
04/A-B	02	SAFETY PIN BOW POLAR SHACKLES	12 TON PER SHACKLE
04/C	01	SAFETY PIN BOW POLAR SHACKLE	2 TON

Previous Test Details

Sheave:	VISUAL	Tested by:	U.I.L.	Cert No.	139899/62	Date:	09/08/2019
---------	--------	------------	--------	----------	-----------	-------	------------

MPI/DPI Inspection Details

Procedure:	QP09:02	Equipment:	Y6 YOKE	Method:	Continuous
Specification:	AWS D1:1	Media:	White Paint	Inspector:	M. YOUNGSON
Material:	Carbon Steel	Indicator:	Black Ink	Quals:	ASNT II
Items Inspected:	Welded Pad Eyes	Quantity:	TWO	Results:	Fit For Use

Declaration: I hereby declare that the above information is correct and the equipment has been thoroughly examined in accordance with the appropriate provisions and is free from defects affecting safety.

	COMPLETED BY	APPROVED BY	ACCEPTED BY
ENGINEER	M. YOUNGSON	N. TRAVIS	<i>J. Patterson</i>
SIGNATURE			
DATE	06/05/2020	06/05/2020	12/05/20

