


Certificate of Visual Inspection of Lifting / Lifted Equipment

Certificate Details						
Certificate No.:	023.1	Job No.:	VER-22-023		Inspection Date:	09/02/2022
Client:	BLUE MANTA	Location:	Blue Manta Yard		Revision Number:	0
INSPECTOR NAME		SIGNATURE		REPORT DATE		
DANIEL LINTHORNE				09/02/2022		
EQUIPMENT DETAILS						
IDENTIFICATION	DESCRIPTION		MGM		INSPECTION SPECIFICATION	RESULT
BM-C-1445	OFFSHORE CONTAINER Tare: 4200 kg Payload: 10000 kg MGM 14200 kg Proofload: BMD-1999-COC/01 rev.1 NDT Due: 03/2025 CCLE BMD-1999-COC/01 rev.1		14200	kg	DNVGL-ST-E271 ISO 10855	Complies at time of inspection

Certificate of Visual Inspection of Lifting / Lifted Equipment

Certificate Details					
Certificate No.:	023.2	Job No.:	VER-22-023	Inspection Date:	09/02/2022
Client:	BLUE MANTA	Location:	Blue Manta Yard	Revision Number:	0
INSPECTOR NAME		SIGNATURE		REPORT DATE	
DANIEL LINTHORNE				09/02/2022	
EQUIPMENT DETAILS					
IDENTIFICATION		DESCRIPTION	WLL	INSPECTION SPECIFICATION	RESULT
BM-C-1445/1		4 leg wire rope sling Heading: HA36QA Wire Size: 28 mm Length: 4000 mm Shackle Size: 9.5 t Declaration of Conformity 39774/1 NDT Due: Jul-25	14.2 t @ 45 °	DNVGL-ST-E271 ISO 10855 EN13414	Complies at time of inspection