



ABERDEEN LIFTING SERVICES LTD

CERTIFICATE OF TEST, EXAMINATION AND INSPECTION REPORT

Provision and use of Work Equipment Regulations-SI 2306

Lifting Operations and Lifting Equipment Regulations- SI 2307

CLIENT:	BLUE MANTA 6 KIRKTON AVENUE PITMEDDEN RD IND EST DYCE ABERDEEN AB21 0BF	TEST HOUSE:	ABERDEEN LIFTING SERVICES LTD UNITS 7&8 WOODLANDS ROAD KIRKHILL INDUSTRIAL ESTATE. DYCE ABERDEEN AB21 0GX TEL: 01224 723333 FAX: 01224 723311
P.O. NO:	2521	REQUISITION NO:	
CERT NO:	A9755-09	INSPECTION DATE:	17/12/2008

SERIAL NO:	QTY	DESCRIPTION	SWL/PAYLOAD	PROOF LOAD
BM-SW-0613	1	UMBILICAL SHEAVE TO DNV RCLA ALL WELDED STEEL CONSTRUCTION C/W CENTRAL LIFTING POINT	3 TONNE 6 TONNE HEAD FITTING	12 TONNE



S. MARSDEN
Witness TESTER
17/12/2008

M.P.I INSPECTION DETAILS				
PROCEDURE:	ALS MPI 01	EQUIPMENT:	Y6 YOKE	METHOD: WET CONTINUOUS
SPECIFICATION:	BS EN 1290	MEDIA:	NPT 16 WHITE PAINT	INSPECTOR: B. SMART
MATERIAL:	WELDED CARBON STEEL	INDICATOR:	BLACK INK	QUALS: SNT 11

RESULTS: A MAGNETIC PARTICLE INSPECTION WAS CARRIED OUT ON LIFTING POINT WELDMENTS. ON THE EQUIPMENT NO CRACK OR CRACKLIKE INDICATIONS WERE NOTED AT TIME OF INSPECTION.

DECLARATION: I HEREBY DECLARE THAT THE ABOVE INFORMATION IS CORRECT AND THE EQUIPMENT HAS BEEN TESTED AND THOROUGHLY EXAMINED IN ACCORDANCE WITH THE APPROPRIATE PROVISIONS AND IS FREE FROM DEFECTS AFFECTING SAFETY.

	COMPLETED BY
ENGINEER	B. SMART
SIGNATURE	
DATE	17/12/2008

NEXT INSPECTION DATE: 16/06/2009
DATE OF MANUFACTURE: DEC 2008

ABERDEEN LIFTING SERVICES LTD

MAGNETIC PARTICLE INSPECTION REPORT


CUSTOMER: BLUE MANTA	LOCATION: ALS YARD
P.O. No: 2521	CERT No: A9755-19
JOB No:	DATE OF INSP: 17/12/2008

JOB DESCRIPTION:

100% MAGNETIC PARTICLE INSPECTION WAS CARRIED OUT PRE & POST LOAD TEST ON ALL LOAD BEARING WELDS

ITEM: UMBILICAL SHEAVE	
QUANTITY: ONE	SURFACE: AS WELDED
SERIAL No: BM-SW-0613	EQUIPMENT: Y6 YOKE
DRG. No: N/A	MEDIA: NPT 16 WHITE PAINT
MATERIAL: CARBON STEEL	INDICATOR: BLACK INK
PROCEDURE: ALS M.P.I. 01	METHOD: WET CONTINUOUS
SPECIFICATION: BS EN 1290	

RESULTS: NO CRACK OR CRACKLIKE INDICATIONS ARE NOTED AT TIME OF INSPECTION.

	COMPLETED BY
ENGINEER/TECHNICIAN	B. SMART
SIGNATURE	
DATE	17/12/2008



CLIENT: BLUE MANTA 6 KIRKTON AVENUE PITMEDDEN RD IND EST DYCE ABERDEEN AB21 0BF	TEST HOUSE: ABERDEEN LIFTING SERVICES LTD UNITS 7&8 WOODLANDS ROAD KIRKHILL INDUSTRIAL ESTATE ABERDEEN AB21 0GX TEL: 01224 723333 FAX: 01224 723311
P.O. No: 2837	REQUISITION No:
CERT No: B1362-01	INSPECTION DATE: 10/02/2009

SERIAL No.	QTY	DESCRIPTION	SWL/ PAYLOAD	PROOF LOAD
6005S-6014S	10	SAFETY PIN BOW SHACKLES	6.5 TONNE	13 TONNE

	COMPLETED BY:
ENGINEER.	D. BRUCE
SIGNATURE.	PP. 9/11/2009
DATE.	10/02/2009

DATE OF MANUFACTURE:
UNKNOWN



CLIENT: BLUE MANTA 6 KIRKTON AVENUE PITMEDDEN RD IND EST DYCE ABERDEEN AB21 0BF	TEST HOUSE: ABERDEEN LIFTING SERVICES LTD UNITS 7&8 WOODLANDS ROAD KIRKHILL INDUSTRIAL ESTATE ABERDEEN AB21 0GX TEL: 01224 723333 FAX: 01224 723311
P.O. No:	REQUISITION No:
CERT No: B1362-03	INSPECTION DATE: 24/02/2009

Declaration: I hereby declare that the above information is correct and the equipment has been tested and thoroughly examined in accordance with the appropriate provisions and is free from defects affecting safety.

NEXT INSPECTION DATE: 23/08/2009
DATE OF MANUFACTURE: UNKNOWN



CLIENT: BLUE MANTA 6 KIRKTON AVENUE PITMEDDEN RD IND EST DYCE ABERDEEN AB21 0BF	TEST HOUSE: ABERDEEN LIFTING SERVICES LTD UNITS 7&8 WOODLANDS ROAD KIRKHILL INDUSTRIAL ESTATE ABERDEEN AB21 0GX TEL: 01224 723333 FAX: 01224 723311
P.O. No:	REQUISITION No:
CERT No: B1362-05	INSPECTION DATE: 24/02/2009

Declaration: I hereby declare that the above information is correct and the equipment has been tested and thoroughly examined in accordance with the appropriate provisions and is free from defects affecting safety.

NEXT INSPECTION DATE: 23/08/2009
DATE OF MANUFACTURE: UNKNOWN