



Certificate of Visual Examination of Lifting and Lifted Equipment - CCU

Certificate Number: P18.0674.9

Client:	Blue Manta 103 Milner Rd High Wycombe WA 6057	Job #:	P18.0674
Location of Inspection:	High Wycombe	Date of Inspection:	20/07/2018

ID	Description of Item	Test / Inspection Specification	Result	MGM
BM-SP-3008	This inspected item consists of the following: Description: Spooler Tare: 600 kg Payload: 900 kg MGM 1500 kg Proof Load: 83392 (07/2009) NDT: PN16.0968.1 (09/2016) CCLE: 83392 (07/2009)	DNV 2.7-1	Complies at time of inspection	1500 kg

Photo (If required)

	Accreditation No: 15255 Accredited for compliance with ISO/IEC 17020	Name of Inspector: Gavin Donnelly Name of Signatory:  Issue Date: Digitally signed by Jim Linthorne Date: 2018.07.23 13:52:52 +08'00'
---	---	---

634 Karel Ave, Jandakot, WA 6164
Unit 1, 92 Spencer St South, Roma, QLD 4455



Certificate of Visual Examination of Lifting and Lifted Equipment – General Rigging

Certificate Number: P18.0674.10

Client:	Blue Manta	Job #:	P18.0674
Location of Inspection:	103 Milner Rd High Wycombe WA 6057	Date of Inspection:	20/07/2018

ID	Description of Item	Test / Inspection Specification	Result	WLL
BM-SP-3008/1	4 leg wire rope sling assembly consisting of the following: 4 Leg Assembly Heading: HA 25 QA Wire Diameter: 19 mm Length: 1100 mm Shackle Size: 4.75 t Proof Load: A9647-28 (12/2008) NDT Cert: PN16.0968.1 (08/2016)	DNV 2.7-1	Complies at time of inspection	1.5 t @ 45°

Photo (If required)

	Accreditation No: 15255 Accredited for compliance with ISO/IEC 17020	Name of Inspector: Gavin Donnelly Name of Signatory Issue Date: <i>9.7/18</i> Digitally signed by Jim Linthorne Date: 2018.07.23 15:39:26 +08'00'
---	--	---

634 Karel Ave, Jandakot, WA 6164
Unit 1, 92 Spencer St South, Roma, QLD 4455