

ABERDEEN LIFTING SERVICES LTD

MAGNETIC PARTICLE INSPECTION REPORT



CUSTOMER: BLUE MANTA	LOCATION: ALS YARD
P.O. No: 18977	CERT No: F6711-06
JOB No:	DATE OF INSP: 11/11/2014

JOB DESCRIPTION:

100% MAGNETIC PARTICLE INSPECTION CARRIED OUT PRE & POST LOAD TEST ON ALL LOAD BEARING WELDS & 20% SECONDARY WELDS

ITEM: SPOOLING UNIT	
QUANTITY: 1	SURFACE: AS WELDED
SERIAL No: BM-SP-3016	EQUIPMENT: Y6 YOKE
DRG No: N/A	MEDIA: NPT 16 WHITE PAINT
MATERIAL: CARBON STEEL	INDICATOR: BLACK INK
PROCEDURE: WI ALNDT.01A REV03	METHOD: WET CONTINUOUS
SPECIFICATION: ASTM E1444/E1444M-11	

RESULTS: NO CRACK OR CRACKLIKE INDICATIONS ARE NOTED AT TIME OF INSPECTION.

	COMPLETED BY
ENGINEER/TECHNICIAN	D.CRAIG
SIGNATURE	
DATE	11/11/2014

