

ABERDEEN LIFTING SERVICES LTD



MAGNETIC PARTICLE INSPECTION REPORT

CUSTOMER: BLUE MANTA	LOCATION: ALS YARD
P.O. No: 22079	CERT No: G7105-03
JOB No:	DATE OF INSP: 08/10/2015

JOB DESCRIPTION:

100% MAGNETIC PARTICLE INSPECTION CARRIED OUT PRE & POST LOAD TEST ON ALL LOAD BEARING WELDS & 20% SECONDARY WELDS

ITEM: SPOOLING UNIT	
QUANTITY: 1	SURFACE: AS WELDED
SERIAL No: BM-SP-3624	EQUIPMENT: Y6 YOKE
DRG. No:	MEDIA: NPT 16 WHITE PAINT
MATERIAL: CARBON STEEL	INDICATOR: BLACK INK
PROCEDURE: WI ALNDT.01A REV03	METHOD: WET CONTINUOUS
SPECIFICATION: ASTM E1444/E1444M-11	

RESULTS: NO CRACK OR CRACKLIKE INDICATIONS ARE NOTED AT TIME OF INSPECTION.

	COMPLETED BY
ENGINEER/TECHNICIAN	B.SMART
SIGNATURE	
DATE	08/10/2015