

ABERDEEN LIFTING SERVICES LTD

CERTIFICATE OF TEST, EXAMINATION AND INSPECTION REPORT

Provision and use of Work Equipment Regulations-SI 2306

Lifting Operations and Lifting Equipment Regulations- SI 2307



CLIENT:	BLUE MANTA 6 KIRKTON AVENUE PITMEDDEN RD IND EST DYCE ABERDEEN AB21 0BF	TEST HOUSE:	ABERDEEN LIFTING SERVICES LTD HOWE MOSS CRESCENT KIRKHILL INDUSTRIAL ESTATE, DYCE ABERDEEN AB21 0GN TEL: 01224 723333 FAX: 01224 723311
P.O. NO:	32265	REQUISITION NO:	
CERT NO:	L3377-01	INSPECTION DATE:	20/08/2019


SERIAL NO:	QTY	DESCRIPTION	SWL/PAYLOAD	PROOF LOAD
BM-SP-6565	1	65" SPOOLING UNIT TO DNV2.7-1 & BSEN12079 2.18M x 1.92M x 2.07M APPROX ALL WELDED STEEL CONSTRUCTION C/W 4 TOP MOUNTED LIFTING POINTS TARE WT: 1600 KGS GROSS WT: 10000 KGS 4 POINT TEST	8400 KGS	25000 KGS

M.P.I INSPECTION DETAILS


PROCEDURE:	WI ALNDT.01A REV05	EQUIPMENT:	Y6 YOKE (NW8744)	METHOD:	WET CONTINUOUS
SPECIFICATION:	ASTM E1444/E144M-16e1 & BSEN ISO 23278:2015 & BSEN ISO 17638:2016	MEDIA:	NPT 16 WHITE PAINT	INSPECTOR:	N.BOWIE
MATERIAL:	WELDED CARBON STEEL	INDICATOR:	BLACK INK	QUALS:	PCN II

RESULTS: A MAGNETIC PARTICLE INSPECTION WAS CARRIED OUT ON LIFTING POINT WELDMENTS. ON THE EQUIPMENT NO CRACK OR CRACKLIKE INDICATIONS WERE NOTED AT TIME OF INSPECTION.

DECLARATION: I HEREBY DECLARE THAT THE ABOVE INFORMATION IS CORRECT AND THE EQUIPMENT HAS BEEN TESTED AND THOROUGHLY EXAMINED IN ACCORDANCE WITH THE APPROPRIATE PROVISIONS AND IS FREE FROM DEFECTS AFFECTING SAFETY.

	COMPLETED BY
ENGINEER	N.BOWIE
SIGNATURE	
DATE	20/08/2019

NEXT INSPECTION DATE: 19/02/2020
DATE OF MANUFACTURE: 08/2019



ABERDEEN LIFTING SERVICES LTD



MAGNETIC PARTICLE INSPECTION REPORT


CUSTOMER: BLUE MANTA	LOCATION: ALS YARD
P.O. No: 32265	CERT No: L3377-03
JOB No:	DATE OF INSP: 20/08/2019

JOB DESCRIPTION:

100% MAGNETIC PARTICLE INSPECTION CARRIED OUT PRE & POST LOAD TEST ON ALL LOAD BEARING WELDS AND 20% SECONDARY WELDS

ITEM: 65" SPOOLING UNIT	
QUANTITY: 1	SURFACE: AS WELDED
SERIAL No: BM-SP-6565	EQUIPMENT: Y6 YOKE (NW8744)
DRG. No: N/A	MEDIA: NPT 16 WHITE PAINT
MATERIAL: CARBON STEEL	INDICATOR: BLACK INK
PROCEDURE: WI ALNDT.01A REV 05	METHOD: WET CONTINUOUS
SPECIFICATION: ASTM E1444/E144M-16e1, BSEN ISO 23278:2015, BSEN ISO 17638:2016	QUALIFICATIONS: PCN II

RESULTS: NO CRACK OR CRACKLIKE INDICATIONS ARE NOTED AT TIME OF INSPECTION.

	COMPLETED BY
ENGINEER/TECHNICIAN	N.BOWIE
SIGNATURE	
DATE	20/08/2019

